

Site: 403 Cheadle Road, Cheddleton
 Surveyed by: Ben Williams BSc (Hons) Arb. M.Arbor.A
 Date: 24/02/2022

Tree Heritage Ltd, Unit 1 Sneyd Mill, Sneyd St, Leek, Staffs, ST13 5HP
 T: 01538 384019 E: info@treeheritage.co.uk



APPENDIX A: TREE SURVEY SCHEDULE

KEY:

Measurements	Life Stage	Physiological Condition	Category Grading	Symbols
Height - Metres Stem Diameter - Millimetres at 1.5m above ground level Branch Spread - Metres (North, South, East and West) Crown Clearance - Metres RPA Radius - Metres Estimated Remaining Contribution - Years FSB - First Significant Branch - Metres	Y - Young SM - Semi-Mature EM - Early Mature M - Mature OM - Over-Mature V - Veteran	G - Good F - Fair P - Poor D - Dead	A - High (green) B - Moderate (blue) C - Low (grey) U - Poor/Trees for removal (red) Sub-Categories: 1 - Mainly Arboricultural value 2 - Mainly Landscape value 3 - Mainly Cultural value	< - Less than ~ - Approximately > - Greater than
RPA - Root protection area (equivalent to a circle with a radius 12x the stem diameter measured at 1.5m above ground level)				

Site: 403 Cheadle Road, Cheddleton

Surveyed by: Ben Williams BSc (Hons) Arb. M.Arbor.A

Date: 24/02/2022

Tree Heritage Ltd, Unit 1 Sneyd Mill, Sneyd St, Leek, Staffs, ST13 5HP

T: 01538 384019 E: info@treeheritage.co.uk

Tree Ref.	Species	Height	Stem Diameter	Branch Spread				Crown Clearance	FSB Height + Direction	Life Stage	Phys. Condition	Structural Condition	Recommendations	Estimated Remaining Contribution	Category Grading	RPA Radius
				N	S	E	W									
T1	Pinus sylvestris (Scots Pine)	14	510	3	6	4	4	6	3(W)	M	Good	Tree located within neighbouring land. Major deadwood in crown.	No work required.	20+	B1	6.12
T2	Chamaecyparis nootkatensis (Nootka Cypress)	14	390	3	3	3	3	2.5	3(S)	M	Fair	Storm damage in crown. Broken branch/es in crown.	Remove tree.	<10	U	4.68
T3	Magnolia (Magnolia)	5	150	2	2	2	2	2.5	1(W)	EM	Good		No work required.	10+	C1	1.8
T4	Malus (Apple)	6	230	3	3	3	3.5	2.5	2(W)	M	Fair	Major deadwood in crown.	No work required.	10+	C1	2.76
T5	Prunus serrulata (Japanese Flowering Cherry)	7	200	3	4	3	1.5	2.5	2(W)	M	Fair	Major deadwood in crown. Root damage. Split stem from historic failure.	No work required.	10+	C1	2.4
T6	Laburnum anagyroides (Laburnum)	7	300	3	3	3	4	2	1(S)	M	Fair	Leaning East.	No work required.	10+	C1	3.6
T7	Prunus domestica (Damson)	4	150	2.5	2.5	2.5	2.5	2	2(N)	M	Fair	Tree located within neighbouring land.	No work required.	10+	C1	1.8
T8	Betula utilis 'Jacquemontii' (Himalayan Birch)	7	150,200, 150	3	3	3	3	2.5	1(N)	EM	Good	Tree located within neighbouring land.	No work required.	10+	B1	3.5
T9	Prunus avium (Wild Cherry)	7	220	4	4	4	4	2	2(N)	M	Fair	Poor shape/form. Ivy on tree. Ivy on stem. Crown distorted due to group pressure.	Remove tree.	<10	U	2.64

Site: 403 Cheadle Road, Cheddleton

Surveyed by: Ben Williams BSc (Hons) Arb. M.Arbor.A

Date: 24/02/2022

Tree Heritage Ltd, Unit 1 Sneyd Mill, Sneyd St, Leek, Staffs, ST13 5HP

T: 01538 384019 E: info@treeheritage.co.uk

Tree Ref.	Species	Height	Stem Diameter	Branch Spread				Crown Clearance	FSB Height + Direction	Life Stage	Phys. Condition	Structural Condition	Recommendations	Estimated Remaining Contribution	Category Grading	RPA Radius
				N	S	E	W									
T10	Chamaecyparis pisifera (Sawara Cypress)	4	200	1.5	1.5	1.5	1.5	0.5	0.5(N)	M	Fair	Poor shape/form.	Remove tree.	<10	U	2.4
T11	Sorbus aucuparia (Rowan)	8	250	2.5	2.5	2	2.5	2	2(S)	M	Fair	Tree located within neighbouring land. Diameter estimated.	No work required.	10+	C1	3
T12	Malus (Apple)	6	220	2	3	3	3	3	3.5(S)	M	Poor	Poor shape/form. Decay present in stem. Broken branch/es in crown.	Remove tree.	<10	U	2.64
T13	Malus (Apple)	7	320	2	3	4.5	4	3	2(S)	M	Fair	Poor shape/form. Decay present in stem. Major deadwood in crown.	No work required.	10+	C1	3.84
T14	Pyrus (Pear)	6	220	1	2	2	1.5	3	2(N)	M	Poor	Poor shape/form. Decay present in stem. Broken branch/es in crown.	Remove tree.	<10	U	2.64
T15	Quercus petraea (Sessile Oak)	15	600	7	6	9	7	6	2(E)	M	Fair	Tree located within neighbouring land. Diameter estimated. Major deadwood in crown.	No work required.	20+	B1	7.2
T16	Acer platanoides (Norway Maple)	12	380	3	5	3	5	4	3.5(N)	EM	Fair	Minor deadwood in crown. Crown distorted due to group pressure.	Remove major deadwood.	10+	C1	4.56

Site: 403 Cheadle Road, Cheddleton

Surveyed by: Ben Williams BSc (Hons) Arb. M.Arbor.A

Date: 24/02/2022

Tree Heritage Ltd, Unit 1 Sneyd Mill, Sneyd St, Leek, Staffs, ST13 5HP

T: 01538 384019 E: info@treeheritage.co.uk

Tree Ref.	Species	Height	Stem Diameter	Branch Spread				Crown Clearance	FSB Height + Direction	Life Stage	Phys. Condition	Structural Condition	Recommendations	Estimated Remaining Contribution	Category Grading	RPA Radius
				N	S	E	W									
T17	Picea abies (Norway Spruce)	12	140	1	1	1	1	8	8(E)	SM	Poor	Poor shape/form. Slender.	Remove tree.	<10	U	1.68
T18	Picea abies (Norway Spruce)	12	300	2	3	3	2	3	3(E)	EM	Fair	Poor shape/form. Crown distorted due to group pressure.	No work required.	10+	C1	3.6
T19	Prunus cerasifera (Cherry Plum)	6	150,100, 100	3	2	2	3	1.5	0.5(N)	M	Fair		No work required.	10+	C1	2.47
T20	Chamaecyparis lawsoniana (Lawson Cypress)	9	300	2.5	2.5	2.5	2.5	0.5	0.5(N)	M	Good		No work required.	10+	C1	3.6
T21	Picea abies (Norway Spruce)	12	320	3	3	3	3	3	3(E)	EM	Fair	Major deadwood in crown.	No work required.	10+	C1	3.84
T22	Quercus petraea (Sessile Oak)	9	360	4	4	6	4	2	1.5(N)	EM	Good	Poor shape/form. Growing in hedgerow.	No work required.	10+	C1	4.32
T23	Quercus petraea (Sessile Oak)	10	200,200, 200,240	4	4	6	4	2	1.5(N)	EM	Good	Poor shape/form. Growing in hedgerow.	No work required.	10+	C1	5.05
T24	Quercus petraea (Sessile Oak)	9	220	2	4	1	3	2.5	2.5(W)	EM	Good	Poor shape/form. Growing in hedgerow.	No work required.	10+	C1	2.64
T25	Betula pendula (Silver Birch)	6	90	1	1	1	1	2	2(W)	SM	Good		No work required.	10+	C1	1.08
T26	Quercus petraea (Sessile Oak)	14	510	8	8	7	8	1	1(S)	M	Good	Major deadwood in crown.	Remove major deadwood over site.	40+	A1	6.12
T27	Betula pendula (Silver Birch)	10	150	2.5	2.5	2.5	2.5	2	2(W)	EM	Good	Tree located within neighbouring land. Diameter estimated.	No work required.	10+	C1	1.8

Site: 403 Cheadle Road, Cheddleton

Surveyed by: Ben Williams BSc (Hons) Arb. M.Arbor.A

Date: 24/02/2022

Tree Heritage Ltd, Unit 1 Sneyd Mill, Sneyd St, Leek, Staffs, ST13 5HP

T: 01538 384019 E: info@treeheritage.co.uk

Tree Ref.	Species	Height	Stem Diameter	Branch Spread				Crown Clearance	FSB Height + Direction	Life Stage	Phys. Condition	Structural Condition	Recommendations	Estimated Remaining Contribution	Category Grading	RPA Radius
				N	S	E	W									
T28	Fagus sylvatica (Beech)	10	230	4	4	4	2	1	2(S)	EM	Good	Tree located within neighbouring land. Low crown over site.	No work required.	20+	B1	2.76
T29	Betula pendula (Silver Birch)	10	150	2.5	2.5	2.5	2.5	2	2(W)	EM	Good	Tree located within neighbouring land. Diameter estimated.	No work required.	10+	C1	1.8
T30	Betula pendula (Silver Birch)	10	180	3	3	3	3	2	2(W)	EM	Good	Tree located within neighbouring land. Diameter estimated.	No work required.	10+	C1	2.16
T31	Cedrus deodora (Deodar)	8	180	4	2	2	3	1	1(N)	EM	Good	Tree located within neighbouring land. Diameter estimated.	No work required.	10+	C1	2.16
G1	Ilex aquifolium (Holly)	3	150	2	2	2	2	0.5	0.5(N)	M	Good	Part of linear group.	No work required.	10+	C1	1.8