



The Coal
Authority

Issued by:

The Coal Authority, Property Search Services, 200 Lichfield Lane, Berry Hill, Mansfield, Nottinghamshire, NG18 4RG
Website: www.groundstability.com Phone: 0345 762 6848

**WARDELL ARMSTRONG LLP
SIR HENRY DOULTON HOUSE
FORGE LANE
STOKE-ON-TRENT
ST1 5BD**

Our reference:	51003064029001
Your reference:	ST29614
Date of your enquiry:	27 April 2022
Date we received your enquiry:	27 April 2022
Date of issue:	27 April 2022

This report is for the property described in the address below and the attached plan.

Shaft Plan and Data Sheets

**VULCAN REFRACTORIES, NEW INDUSTRIAL UNIT, DRAYCOTT CLOSE ROAD,
BROOKHOUSES INDUSTRIAL ESTATE, CHEADLE, STAFFORDSHIRE, ST10 1PN**

I refer to the enquiry dated 27 April 2022, received 27 April 2022, in connection with the above.


As requested I enclose the mine entry data sheet(s) held for the mine entry/entries referred to.

Mine Entry Data

Shaft/adit:	Adit
Reference:	399342-058
Source:	6inch Geological Survey map
Colliery name:	Unknown
Entry name:	Unknown
Date abandoned:	Unknown
Depth of superficial deposits (m):	Unknown
Depth of shaft (m):	Unknown
Diameter of shaft (m):	Unknown
Probable adit azimuth:	259
Treatment details:	Unknown
Conveyance:	Not Applicable
Easting:	399694
Northing:	342709
Other information:	None

Location map

Approximate position of enquiry



Reproduced by permission of Ordnance Survey on behalf of HMSO.
© Crown copyright and database right 2018. All rights reserved.
Ordnance Survey Licence number: 100020315

This plan shows the approximate location of the disused mine entry / entries referred to in the attached mining report. For reasons of clarity, mine entry symbols may not be drawn to the same scale as the plan.

Property owners have the benefit of statutory protection (under the Coal Mining Subsidence Act 1991). This contains provision for the making good, to the reasonable satisfaction of the owner, of physical damage from disused coal mine workings including disused coal mine entries. A leaflet setting out the rights and obligations of either the Coal Authority or other responsible persons under the 1991 Act can be obtained by visiting www.groundstability.com.

If you wish to discuss the relevance of any of the information contained in this report, you should seek the advice of a qualified mining engineer or surveyor. If you or your advisor wish to examine the source plans from which the information has been taken, these are available to view, free of charge, at our Head Office in Mansfield. To book an appointment please ring 01623 637225. Should you or your advisor wish to carry out a physical investigation that may enter, disturb or interfere with any disused mine entry, prior permission of the owner must be sought. For coal mine entries, the owner will normally be the Coal Authority.

The Coal Authority, regardless of responsibility and in conjunction with other public bodies, provide an emergency call out facility in coalfield areas to assess the public safety implications of mining features (including disused mine entries).

Our emergency telephone number is 0800 288 4242.

Key

Disused Adit or Mineshaft

