

Proposed Door Cill and Lintel Schedule							
Mark	Type	Cill Retained	Cill Replaced	Cill Comment	Lintel Retained	Lintel Replaced	Lintel Comment
D0.01	Door Type 1			Not Applicable	Yes		
D0.03	Door Type 2			Not Applicable	Yes		
D0.05	Door Type 5			Not Applicable		Yes	New lintel to match existing stone lintels
D0.09	Door Type 1A			Not Applicable	Yes		As W0.09
D1.01	Door Type 5A	Yes			Yes		
D2.01	Door Type 5B	Yes			Yes		
D3.01	Door Type 5C	Yes			Yes		
SSD0.01	Door Type 2372.5			Not Applicable	Yes		
SSD0.02	Door Type 1472.5			Not Applicable	Yes		

Proposed Window Cill and Lintel Schedule							
Mark	Type	Cill Retained	Cill Replaced	Cill Comment	Lintel Retained	Lintel Replaced	Lintel Comment
DW0.01	Above D0.01						
DW0.03	Above D0.03						
DW0.05	Above D0.05						
DW0.09	Above D0.09						
DW0.09A	Beside D0.09	No	No	Cill removed to form D0.01	Yes		
DW0.09B	Window Type 1	Yes			Yes		
DW1.01	Above D1.01						
DW2.01	Above D2.01						
W0.01	Window Type 1	Yes		Subject to S.E comment/ West elevation works	Yes		Subject to S.E Comment/ West elevation works
W0.02	Window Type 1	Yes			Yes		
W0.03	Window Type 1	Yes			Yes		
W0.04	Window Type 1	Yes			Yes		
W0.05	Window Type 1	Yes			Yes		
W0.06	Window Type 1	Yes			Yes		
W0.07	Window Type 1	Yes			Yes		
W0.08	Window Type 1	Yes			Yes		
W0.10	Window Type 1	Yes			Yes		
W0.11	Window Type 1	Yes			Yes		
W0.12	Window Type 1		Yes	New cill to suit reduced opening size to match existing stone cills		Yes	New lintel to suit reduced opening size to match existing stone lintels
W0.13	Window Type 1	Yes			Yes		
W0.14	Window Type 1	Yes			Yes		
W0.15	Window Type 1	Yes			Yes		
W0.16	Window Type 1	Yes			Yes		
W0.17	Window Type 1	Yes			Yes		
W0.18	Window Type 1	Yes			Yes		
W0.19	Window Type 1	Yes			Yes		
W0.20	Type 1A	Yes			Yes		
W0.21	Window Type 2		Yes	New cill to match existing stone cills	Yes		
W0.22	Window Type 2	Yes				Yes	New lintel at reduced height to match existing stone lintels
W0.23	Window Type 2	Yes				Yes	New lintel at reduced height to match existing stone lintels
W0.24	Window Type 2	Yes			Yes		New lintel at reduced height to match existing stone lintels
W0.25	Window Type 1	Yes				Yes	New lintel at reduced height to match existing stone lintels
W0.26	Window Type 1	Yes				Yes	New lintel at reduced height to match existing stone lintels
W0.27	Window Type 1	Yes			Yes		New lintel at reduced height to match existing stone lintels
W0.28	Window Type 1	Yes			Yes		
W0.29	Window Type 1	Yes				Yes	New lintel to match existing stone lintels
W0.30	Window Type 1		Yes	New cill to match existing stone cills	Yes		
W0.31	Window Type 1		Yes	New cill to match existing stone cills	Yes		
W0.32	Window Type 1		Yes	New cill to match existing stone cills	Yes		
W0.33	Window Type 1		Yes	New cill to match existing stone cills	Yes		
W0.34	Window Type 1	Yes			Yes		
W0.35	Window Type 1		Yes	New cill to match existing stone cills	Yes		
W0.36	Window Type 1		Yes	New cill to match existing stone cills	Yes		
W0.37	Window Type 1		Yes	New cill to match existing stone cills	Yes		
W0.38	Window Type 1		Yes	New cill to match existing stone cills	Yes		Subject to S.E Comment/ West elevation works
W0.39	Window Type 1	Yes		Subject to S.E comment/ West elevation works		Yes	As per S.E notes
W0.40	Window Type 1	Yes		Subject to S.E comment/ West elevation works	Yes		Subject to S.E Comment/ West elevation works
W0.41	Window Type 1		Yes	New cill to suit increased opening size to match existing stone cills	No	Yes	As per S.E notes
W1.01	Window Type 1	Yes		Subject to S.E comment/ West elevation works	Yes		Subject to S.E Comment/ West elevation works
W1.02	Window Type 1	Yes			Yes		
W1.03	Window Type 1	Yes			Yes		
W1.04	Window Type 1	Yes			Yes		
W1.05	Window Type 1	Yes			Yes		
W1.06	Window Type 1	Yes			Yes		
W1.07	Window Type 1	Yes			Yes		
W1.08	Window Type 1	Yes			Yes		
W1.09	Window Type 1	Yes			Yes		
W1.10	Window Type 1	Yes			Yes		
W1.11	Window Type 1	Yes			Yes		
W1.12	Window Type 1	Yes			Yes		
W1.13	Window Type 1	Yes			Yes		
W1.14	Window Type 1	Yes			Yes		
W1.15	Window Type 1	Yes			Yes		
W1.16	Window Type 1	Yes			Yes		
W1.17	Window Type 1	Yes			Yes		
W1.18	Window Type 1	Yes			Yes		
W1.19	Window Type 1	Yes			Yes		
W1.20	Window Type 1	Yes			Yes		
W1.20A	Window Type 1		Yes	New cill to match existing stone cills	Yes		
W1.21	Window Type 1	Yes			Yes		
W1.22	Window Type 1	Yes			Yes		
W1.23	Window Type 1	Yes			Yes		
W1.24	Window Type 1	Yes			Yes		
W1.25	Window Type 1	Yes			Yes		
W1.26	Window Type 1	Yes			Yes		
W1.27	Window Type 1	Yes			Yes		
W1.28	Window Type 1	Yes			Yes		
W1.29	730 x1230mm	Yes			Yes		
W1.30	Window Type 1AOV				Yes		
W1.31	Window Type 1	Yes			Yes		
W1.32	Window Type 1	Yes			Yes		
W1.32A	Window Type 1		Yes	New cill to match existing stone cills	Yes	Yes	Upper lintel retained, lower lintel removed with brickwork to fill
W1.33	Window Type 1	Yes			Yes		
W1.34	Window Type 1	Yes			Yes		
W1.35	Window Type 1	Yes			Yes		
W1.36	Window Type 1	Yes			Yes		

Proposed Window Cill and Lintel Schedule							
Mark	Type	Cill Retained	Cill Replaced	Cill Comment	Lintel Retained	Lintel Replaced	Lintel Comment
W1.37	Window Type 1	Yes			Yes		
W1.38	Window Type 1	Yes			Yes		
W1.39	Window Type 1	Yes		Subject to S.E comment/ West elevation works	Yes		Subject to S.E Comment/ West elevation works
W1.40	Window Type 1	Yes		Subject to S.E comment/ West elevation works	Yes		Subject to S.E Comment/ West elevation works
W1.41	Window Type 1	Yes		Subject to S.E comment/ West elevation works	Yes		Subject to S.E Comment/ West elevation works
W1.42	Window Type 1		Yes	New cill to match existing stone cills	Yes		Subject to S.E Comment/ West elevation works - ensure existing lintel is wide enough for replacement window
W2.01	Window Type 1	Yes		Subject to S.E comment/ West elevation works	Yes		Subject to S.E Comment/ West elevation works
W2.02	Window Type 1	Yes			Yes		
W2.03	Window Type 1	Yes			Yes		
W2.04	Window Type 1	Yes			Yes		
W2.05	Window Type 1	Yes			Yes		
W2.06	Window Type 1	Yes			Yes		
W2.07	Window Type 1	Yes			Yes		
W2.08	Window Type 1	Yes			Yes		
W2.09	Window Type 1	Yes			Yes		
W2.10	Window Type 1	Yes			Yes		
W2.11	Window Type 1	Yes			Yes		
W2.12	Window Type 1	Yes			Yes		
W2.13	Window Type 1	Yes			Yes		
W2.14	Window Type 1	Yes			Yes		
W2.15	Window Type 1	Yes			Yes		
W2.16	Window Type 1	Yes			Yes		
W2.17	Window Type 1	Yes			Yes		
W2.18	Window Type 1	Yes			Yes		
W2.19	Window Type 1	Yes			Yes		
W2.20	Window Type 1	Yes			Yes		
W2.21	Window Type 1	Yes			Yes		
W2.22	Window Type 1	Yes			Yes		
W2.23	Window Type 1	Yes			Yes		
W2.24	Window Type 1	Yes			Yes		
W2.25	Window Type 1	Yes			Yes		
W2.26	Window Type 1	Yes			Yes		
W2.27	Window Type 1	Yes			Yes		
W2.28	Window Type 1	Yes			Yes		
W2.29	Window Type 1	Yes			Yes		
W2.30	Window Type 3	Yes			Yes		
W2.31	Window Type 1AOV	Yes			Yes		
W2.32	Window Type 1	Yes			Yes		
W2.33	Window Type 1	Yes			Yes		
W2.34	Window Type 1	Yes			Yes		
W2.35	Window Type 1	Yes			Yes		
W2.36	Window Type 1	Yes			Yes		
W2.37	Window Type 1	Yes			Yes		
W2.38	Window Type 1	Yes			Yes		
W2.39	Window Type 1	Yes			Yes		
W2.40	Window Type 1	Yes			Yes		
W2.41	Window Type 1	Yes		Subject to S.E comment/ West elevation works	Yes		Subject to S.E Comment/ West elevation works
W2.42	Window Type 1	Yes		Subject to S.E comment/ West elevation works	Yes		Subject to S.E Comment/ West elevation works
W2.43	Window Type 1	Yes		Subject to S.E comment/ West elevation works	Yes		Subject to S.E Comment/ West elevation works
W2.44	Window Type 1		Yes	New cill to match existing stone cills	Yes		Subject to S.E Comment/ West elevation works - ensure existing lintel is wide enough for replacement window
W3.01	Window Type 5	Yes		Subject to S.E comment/ West elevation works	Yes		Subject to S.E Comment/ West elevation works
W3.02	Window Type 5	Yes			Yes		
W3.03	Window Type 5	Yes			Yes		
W3.04	Window Type 5	Yes			Yes		
W3.05	Window Type 5	Yes			Yes		
W3.06	Window Type 5	Yes			Yes		
W3.07	Window Type 5	Yes			Yes		
W3.08	Window Type 5	Yes			Yes		
W3.09	Window Type 5	Yes			Yes		
W3.10	Window Type 5	Yes			Yes		
W3.11	Window Type 5	Yes			Yes		
W3.12	Window Type 5	Yes			Yes		
W3.13	Window Type 5	Yes			Yes		
W3.14	Window Type 5	Yes			Yes		
W3.15	Window Type 5	Yes			Yes		
W3.16	Window Type 5	Yes			Yes		
W3.17	Window Type 5	Yes			Yes		
W3.18	Window Type 5	Yes			Yes		
W3.19	Window Type 5	Yes			Yes		
W3.20	Window Type 5	Yes			Yes		
W3.21	Window Type 5	Yes			Yes		
W3.22	Window Type 5	Yes			Yes		
W3.23	Window Type 5	Yes			Yes		
W3.24	Window Type 5	Yes			Yes		
W3.25	Window Type 5	Yes			Yes		
W3.26	Window Type 5	Yes			Yes		
W3.27	Window Type 5	Yes			Yes		
W3.28	Window Type 5	Yes			Yes		
W3.29	Window Type 5	Yes			Yes		
W3.30	Window Type 3	Yes			Yes		
W3.31	Window Type 5AOV	Yes			Yes		
W3.32	Window Type 5	Yes				Yes	As per S.E notes
W3.33	Window Type 5	Yes			Yes		
W3.34	Window Type 5	Yes			Yes		
W3.35	Window Type 5	Yes			Yes		
W3.36	Window Type 5	Yes			Yes		
W3.37	Window Type 5	Yes			Yes		
W3.38	Window Type 5	Yes			Yes		
W3.39	Window Type 5	Yes			Yes		
W3.40	Window Type 5	Yes			Yes		
W3.41	Window Type 5	Yes		Subject to S.E comment/ West elevation works	Yes		Subject to S.E Comment/ West elevation works
W3.42	Window Type 5	Yes		Subject to S.E comment/ West elevation works	Yes		Subject to S.E Comment/ West elevation works
W3.43	Window Type 5	Yes		Subject to S.E comment/ West elevation works	Yes		Subject to S.E Comment/ West elevation works
W3.44	Window Type 5	Yes		Subject to S.E comment/ West elevation works	Yes		Subject to S.E Comment/ West elevation works
W4.01	Window Type 6	Yes			Yes		

General Notes

1. This drawing is subject to Copyright & must not be copied or reproduced without consent.
2. Only Figured dimensions only are to be taken from this drawing. DO NOT SCALE FOR CONSTRUCTION PURPOSES.
3. All contractors must visit the site and be responsible for taking and checking all dimensions relative to their work prior to the commencement on site. Any errors are to be reported to inc Architects Ltd.
4. This Drawing should be read in conjunction with all relevant Engineers & Specialists drawings and specifications.
5. All new works to be carried out are to comply with the latest editions of the building regulations and all subsequent amendments.
6. All materials are to be fixed in strict accordance with the manufacturers written instructions and recommendations and the relevant British standards and code of practice.
7. The contractor shall check all dimensions, pitches and site surroundings prior to commencing work.
8. All dimensions are in millimetres unless otherwise stated.
9. All structural information should be as per the Structural Engineers Design and Specification
10. The Contractor shall be responsible for the execution of the works in accordance with the drawings and the specification and for the accuracy of all dimensions and setting out on site.
11. Should there be any conflict between the details indicated on this drawing and those indicated on other drawings the Architect shall be informed PRIOR to construction on site.
12. Until technical approval has been obtained from the relevant Building Control Authority, all drawings issued are Preliminary and NOT for construction. Should the Contractor commence site work prior to such approval being given, it is entirely at their own risk.
13. N.B. inc Architects Ltd are not appointed as Principal Designer on any works on this project, as described under the Construction (Design and Management) and The Building Regulations 2010 (Building Regulations) as amended by The Building Regulations etc. (Amended) (England) Regulations 2023.

Cill and Lintel Specification

•The cill and lintel schedule indicates some of the lintels and cills would be replaced or altered for the changes in opening sizes. It would be useful to have some more technical details on the material and detailing of any replacements to ensure that this is sympathetic to the appearance of the building.

Cills
All new or replacement cills are to match existing stone cills in material and profile as 'like for like' replacements.

Lintels
All new or replacement Lintels are to match existing stone Lintels in material and profile as 'like for like' replacements.

General
OPENING SIZES TO BE CHECKED ON SITE PRIOR TO PLACING OF ORDER OR COMMENCEMENT OF MANUFACTURE OF UNITS.

Window/Doors units to be fixed in accordance with window manufacturers recommendations & design.

All structural support requirements to be confirmed by manufacturer & Structural Engineer, including the condition of existing Lintels and Cills.

C	Feb 2026	DD	Detail added in response to Conservation Comments
B	Dec 2025	DD	Titleblock change to suit planning comment
A	Dec 2025	DD	Planning Discharge
Rev	Date	By	Detail



59 Piccadilly, Piccadilly, Hanley, Stoke-on-Trent, ST1 1HR
www.incarchitects.co.uk



RIBA
Chartered Practice

Client

Vanguard Group Developments (UK3) Limited

Project

Proposed Conversion/Development at:

London Mill, Ashbourne Road, ST13 5AS

Drawing status

RIBA Stage 4 - Planning Disharge

Drawing title

Cill and Lintel Schedule

Drawing number

25 031 - INC - DR