

AccsMap - Accident Analysis Syster
Accidents between dates **01/05/2007 and 30/04/2012** (60) months

Selection:

Selected using Manual Selection

Notes:

Acc. Ref. No:	07013117	Road:	A 50	Grid Reference:	396370 340560
District Council:	Staffordshire Moorland	Time:	0733		Thursday 24-May-2007
Lighting:	Daylight:street lights present	Weather:	Fine without high winds	Speed limit:	70
Severity:	SLIGHT	Road surface	Dry		
Location:	A50 APPROX 20 MTRS N J/W A521 BLYTHE BRIDGE				

The accident occurred at a roundabout on the A50, at its junction with the A521 controlled by a give way or uncontrolled..

Special conditions and hazards: None

Vehicle 1 Goods 7.5 tonnes mgw and over, travelling from W to SE was going ahead on a right bend on the main carriageway. The vehicle was mid junction - on roundabout or main road and overturned and collided with vehicle 2.
 The female driver aged 42 lived in ST6 had regularly travelled through the site before.

Vehicle 2 Car, travelling from E to W was going ahead but held up on the main carriageway. The vehicle was entering roundabout and collided with vehicle 1. The male driver aged 40 lived in ST10 had regularly travelled through the site before.

Vehicle 3 Car, travelling from E to W was going ahead but held up on the main carriageway. The vehicle was entering roundabout and collided with vehicle 1. The female driver aged 35 lived in ST10 had regularly travelled through the site before.

Casualty 1 (Vehicle 1) A female driver aged 42 suffered a slight injury.

Casualty 2 (Vehicle 2) A male driver aged 40 suffered a slight injury.

Casualty 3 (Vehicle 3) A female driver aged 35 suffered a slight injury.

Contributory Factors

Vehicle 1 Road layout (eg bend, hill etc.)

Acc. Ref. No:	07019683	Road:	A 50	Grid Reference:	396380 340480
District Council:	Staffordshire Moorland	Time:	1654		Friday 27-July-2007
Lighting:	Daylight: no street lighting	Weather:	Fine without high winds	Speed limit:	70
Severity:	SLIGHT	Road surface	Dry		
Location:	A50 W/B APPROX 34MTRS SE J/W A521 BLYTHE BRIDGE				

The accident occurred on the A50, a dual carriageway .

Special conditions and hazards: None

Vehicle 1 Car, travelling from SE to W was changing lane to right on the main carriageway. The vehicle was not at, or within 20M of a junction and collided with vehicle 2. The male driver aged 25 lived in ST6 had regularly travelled through the site before.

Vehicle 2 Car, travelling from SE to W was changing lane to left on the main carriageway. The vehicle was not at, or within 20M of a junction and collided with vehicle 1. The male driver aged 29 lived in M22 had regularly travelled through the site before.

Casualty 1 (Vehicle 1) A male driver aged 25 suffered a slight injury.

Casualty 2 (Vehicle 2) A male driver aged 29 suffered a slight injury.

Casualty 3 (Vehicle 2) A male vehicle or pillion passenger aged 19 suffered a slight injury.

Contributory Factors

Vehicle 1 Failed to look properly

Vehicle 2 Failed to look properly

Acc. Ref. No:	07021140	Road:	C 13	Grid Reference:	397180 338820
District Council:	Staffordshire Moorland	Time:	0630		Saturday 11-August-2007
Lighting:	Daylight: no street lighting	Weather:	Fine without high winds	Speed limit:	40
Severity:	SLIGHT	Road surface	Dry		
Location:	SANDON RD CRESSWELL APPROX 100MTRS S J/W ROOKERY CRES.				

The accident occurred on the C13, a single carriageway .

Special conditions and hazards: Road works

Vehicle 1 Car, travelling from NE to SW was going ahead other on the main carriageway. The vehicle was not at, or within 20M of a junction and skidded. The female driver aged 47 lived in ST10 had regularly travelled through the site before.

Casualty 1 (Vehicle 1) A female driver aged 47 suffered a slight injury.

Contributory Factors

Vehicle 1 Deposit on road (eg oil, mud, chippings)

Vehicle 1 Animal or object in carriageway

Vehicle 1 Swerved

AccsMap - Accident Analysis Syster
Accidents between dates **01/05/2007 and 30/04/2012** (60) months

Selection:

Selected using Manual Selection

Notes:

Acc. Ref. No:	07022181	Road:	C 109	Grid Reference:	397190	340520
District Council:	Staffordshire Moorland	Time:	1330	Weather:	Wednesday	22-August-2007
Lighting:	Daylight: no street lighting	Weather:	Fine without high winds	Speed limit:	40	
Severity:	SLIGHT	Road surface	Dry			
Location:	UTTOXETER RD J/W STUART AVE DRAYCOTT IN THE MOORS					

The accident occurred at a T or staggered junction on the C109, a single carriageway at its junction with the Unclassified206 controlled by a give way or uncontrolled..

Special conditions and hazards: None

Vehicle 1 Car, travelling from W to E was going ahead other on the main carriageway. The vehicle was approaching junction or waiting/parked at junction approach and collided with vehicle 2.

The male driver aged 20 lived in WS14 had occasionally travelled through the site before.

Vehicle 2 Car, travelling from W to N was turning left on the main carriageway. The vehicle was mid junction - on roundabout or main road and overturned and collided with vehicle 1.

The male driver aged 20 lived in ST11 had regularly travelled through the site before.

Casualty 1 (Vehicle 1) A male vehicle or pillion passenger aged 12 suffered a slight injury.

Contributory Factors

Vehicle 1 Following too close
 Vehicle 1 Exceeding speed limit
 Vehicle 2 Failed to signal/Misleading signal
 Vehicle 1 Sudden braking
 Vehicle 1 Careless/Reckless/In a hurry

Acc. Ref. No:	07026460	Road:	A 521	Grid Reference:	396400	340560
District Council:	Staffordshire Moorland	Time:	0800	Weather:	Monday	08-October-2007
Lighting:	Daylight:street lights present	Weather:	Fine without high winds	Speed limit:	60	
Severity:	SLIGHT	Road surface	Dry			
Location:	UTTOXETER RD APPROX 15MTRS E J/W A50 BLYTHE BRIDGE					

The accident occurred at a roundabout on the A521, a dual carriageway at its junction with the A50 controlled by a stop sign..

Special conditions and hazards: None

Vehicle 1 Motor Cycle over 50 cc and up to 125cc, travelling from E to W was stopping on the main carriageway. The vehicle was approaching junction or waiting/parked at junction approach.

The male driver aged 17 lived in ST10 had regularly travelled through the site before.

Casualty 1 (Vehicle 1) A male pedestrian age unknown suffered a slight injury crossing from driver's offside masked3.

Contributory Factors

Casualty 1 Crossed road masked by stationary veh
 Vehicle 1 Inexperienced or learner driver/rider

Acc. Ref. No:	07026467	Road:	A 50	Grid Reference:	396380	340540
District Council:	Staffordshire Moorland	Time:	0755	Weather:	Wednesday	10-October-2007
Lighting:	Daylight: no street lighting	Weather:	Fine without high winds	Speed limit:	60	
Severity:	SLIGHT	Road surface	Dry			
Location:	BLYTHE BRIDGE R'BOUT J/W UTTOXETER RD					

The accident occurred at a roundabout on the A50, at its junction with the A521 controlled by a give way or uncontrolled..

Special conditions and hazards: Road surface defective

Vehicle 1 Goods 7.5 tonnes mgw and over, travelling from W to SE was turning right on the main carriageway. The vehicle was leaving roundabout and overturned and collided with vehicle 2.

The male driver aged 24 lived in LL21 had occasionally travelled through the site before.

Vehicle 2 Car, travelling from NE to W was going ahead other on the main carriageway. The vehicle was entering roundabout and collided with vehicle 1. The female driver aged 23 lived in ST11 had regularly travelled through the site before.

Vehicle 3 Car, travelling from NE to W was going ahead other on the main carriageway. The vehicle was entering roundabout and collided with vehicle 1. The male driver aged 27 lived in ST10 had regularly travelled through the site before.

Vehicle 4 Goods 7.5 tonnes mgw and over, travelling from NE to W was going ahead but held up on the main carriageway. The vehicle was entering roundabout and collided with vehicle 2.

The male driver aged 38 lived in ST10 had regularly travelled through the site before.

Casualty 1 (Vehicle 1) A male driver aged 24 suffered a slight injury.

Casualty 2 (Vehicle 2) A female driver aged 23 suffered a slight injury.

Casualty 3 (Vehicle 3) A male driver aged 27 suffered a slight injury.

Casualty 4 (Vehicle 3) A female vehicle or pillion passenger aged 23 suffered a slight injury.

Contributory Factors

Vehicle 1 Poor or defective road surface
 Vehicle 1 Road layout (eg bend, hill etc.)
 Vehicle 1 Poor turn or manoeuvre

AccsMap - Accident Analysis Syster
Accidents between dates **01/05/2007 and 30/04/2012** (60) months

Selection:

Selected using Manual Selection

Notes:

Acc. Ref. No:	07027226	Road:	A 50	Grid Reference:	396370	340510
District Council:	Staffordshire Moorland	Time:	0710		Monday	15-October-2007
Lighting:	Daylight: street lighting unknown	Weather:	Fine without high winds	Speed limit:	70	
Severity:	SLIGHT	Road surface	Wet/Damp			

Location: A50 R/B J/W UTTOXETER RD STONEHOUSES

The accident occurred at a roundabout on the A50, at its junction with the A521 controlled by a give way or uncontrolled..

Special conditions and hazards: None

Vehicle 1 Car, travelling from SE to NW was starting on the main carriageway. The vehicle was entering roundabout and collided with vehicle 2. The female driver aged 50 lived in ST11.

Vehicle 2 Motorcycle 50cc and under, travelling from SE to NW was starting on the main carriageway. The vehicle was entering roundabout and collided with vehicle 1. The male driver aged 44 lived in ST11.

Casualty 1 (Vehicle 2) A male rider aged 44 suffered a slight injury.

Contributory Factors

Vehicle 2 Failed to judge other persons path or speed

Vehicle 2 Failed to look properly

Acc. Ref. No:	07026875	Road:	A 521	Grid Reference:	396700	340690
District Council:	Staffordshire Moorland	Time:	1705		Wednesday	17-October-2007
Lighting:	Daylight: no street lighting	Weather:	Fine without high winds	Speed limit:	60	
Severity:	SLIGHT	Road surface	Dry			

Location: UTTOXETER RD JUNC TO UTTOXETER RD BLYTHE BRIDGE

The accident occurred at a T or staggered junction on the A521, a dual carriageway at its junction with the A521 controlled by a give way or uncontrolled..

Special conditions and hazards: None

Vehicle 1 Car, travelling from E to N was starting on the main carriageway. The vehicle was mid junction - on roundabout or main road and skidded and collided with vehicle 2. The male driver aged 23 lived in ST2 had not travelled through the site before.

Vehicle 2 Car, travelling from W to E was going ahead other on the main carriageway. The vehicle was mid junction - on roundabout or main road and skidded and collided with vehicle 1. The male driver aged 19 had not travelled through the site before.

Casualty 1 (Vehicle 1) A male driver aged 23 suffered a slight injury.

Casualty 2 (Vehicle 2) A male driver aged 19 suffered a slight injury.

Casualty 3 (Vehicle 1) A female vehicle or pillion passenger aged 24 suffered a slight injury.

Contributory Factors

Vehicle 1 Failed to look properly

Vehicle 1 Failed to judge other persons path or speed

Acc. Ref. No:	07030047	Road:	C 109	Grid Reference:	398000	340160
District Council:	Staffordshire Moorland	Time:	2151		Monday	26-November-2007
Lighting:	Darkness: street lights present and lit	Weather:	Raining without high winds	Speed limit:	40	
Severity:	SLIGHT	Road surface	Wet/Damp			

Location: UTTOXETER RD J/W CRESSWELL LANE DRAYCOTT IN THE MOORS

The accident occurred at a T or staggered junction on the C109, a single carriageway at its junction with the C13 controlled by a give way or uncontrolled..

Special conditions and hazards: None

Vehicle 1 Car, travelling from SW to NE was starting on the main carriageway. The vehicle was entering main road and skidded and collided with vehicle 2. The male driver aged 17 lived in ST11.

Vehicle 2 Car, travelling from SE to NW was going ahead other on the main carriageway. The vehicle was mid junction - on roundabout or main road and skidded and collided with vehicle 1. The female driver aged 54 lived in ST14.

Casualty 1 (Vehicle 2) A female vehicle or pillion passenger aged 18 suffered a slight injury.

Contributory Factors

Vehicle 1 Junction overshoot

Vehicle 1 Sudden braking

Vehicle 1 Loss of control

AccsMap - Accident Analysis Syster
Accidents between dates **01/05/2007 and 30/04/2012** (60) months

Selection:

Selected using Manual Selection

Notes:

Acc. Ref. No:	07031098	Road:	C 109	Grid Reference:	398010	340160
District Council:	Staffordshire Moorland	Time:	2230		Thursday	13-December-2007
Lighting:	Darkness: street lights present and lit	Weather:	Fine without high winds	Speed limit:	40	
Severity:	SLIGHT	Road surface	Frost/Ice			
Location:	UTTOXETER RD J/W CRESSWELL LANE					

The accident occurred at a T or staggered junction on the C109, a single carriageway at its junction with the C13 controlled by a give way or uncontrolled..

Special conditions and hazards: None

Vehicle 1 Car, travelling from SW to SE was turning right on the main carriageway. The vehicle was mid junction - on roundabout or main road and collided with vehicle 2. The male driver aged 23 lived in ST10 had regularly travelled through the site before.

Vehicle 2 Car, travelling from SE to NW was going ahead other on the main carriageway. The vehicle was approaching junction or waiting/parked at junction approach and collided with vehicle 1. The male driver aged 45 lived in ST11.

Casualty 1 (Vehicle 2) A female vehicle or pillion passenger aged 45 suffered a slight injury.

Casualty 2 (Vehicle 2) A female vehicle or pillion passenger aged 17 suffered a slight injury.

Contributory Factors

Vehicle 1 Junction overshoot

Acc. Ref. No:	08009429	Road:	A 50	Grid Reference:	397780	339690
District Council:	Staffordshire Moorland	Time:	1635		Tuesday	29-April-2008
Lighting:	Daylight:street lights present	Weather:	Fine without high winds	Speed limit:	60	
Severity:	SLIGHT	Road surface	Dry			
Location:	A50 WESTBOUND BLYTHE BRIDGE					

The accident occurred on the A50, a dual carriageway .

Special conditions and hazards: None

Vehicle 1 Car, travelling from E to W was going ahead other on the main carriageway. The vehicle was not at, or within 20M of a junction and collided with vehicle 2. The male driver aged 45 lived in ST11 had regularly travelled through the site before.

Vehicle 2 Car, travelling from E to W was stopping on the main carriageway. The vehicle was not at, or within 20M of a junction and collided with vehicle 1. The male driver aged 61 lived in ST11 had regularly travelled through the site before.

Casualty 1 (Vehicle 1) A male driver aged 45 suffered a slight injury.

Contributory Factors

Vehicle 2 Distraction in vehicle

Vehicle 1 Following too close

Vehicle 1 Failed to judge other persons path or speed

Acc. Ref. No:	08011140	Road:	A 50	Grid Reference:	396380	340540
District Council:	Staffordshire Moorland	Time:	1810		Thursday	29-May-2008
Lighting:	Daylight:street lights present	Weather:	Fine without high winds	Speed limit:	60	
Severity:	SLIGHT	Road surface	Dry			
Location:	A50 R/B A521 UTTOXETER ROAD BLYTHE BRIDGE					

The accident occurred at a roundabout on the A50, at its junction with the A521 controlled by a give way or uncontrolled..

Special conditions and hazards: None

Vehicle 1 Goods 7.5 tonnes mgw and over, travelling from SW to SE was turning right on the main carriageway. The vehicle was leaving roundabout and skidded and overturned. The male driver aged 41 lived in G84 .

Casualty 1 (Vehicle 1) A male driver aged 41 suffered a slight injury.

Contributory Factors

Vehicle 1 Road layout (eg bend, hill etc.)

AccsMap - Accident Analysis Syster
Accidents between dates **01/05/2007 and 30/04/2012** (60) months

Selection:

Selected using Manual Selection

Notes:

Acc. Ref. No:	08011769	Road:	C 109	Grid Reference:	398110	340120
District Council:	Staffordshire Moorland	Time:	1730		Tuesday	03-June-2008
Lighting:	Daylight:street lights present	Weather:	Fine without high winds	Speed limit:	40	
Severity:	SLIGHT	Road surface	Dry			
Location:	UTTOXETER ROAD O/S ENT TO MANOR FARM DRAYCOTT IN THE MOORS					

The accident occurred at a private drive on the C109, a single carriageway at its junction with the Unclassified0 controlled by a give way or uncontrolled..

Special conditions and hazards: None

Vehicle 1 Car, travelling from SE to NW was going ahead other on the main carriageway. The vehicle was approaching junction or waiting/parked at junction approach and collided with vehicle 2. The male driver aged 43 lived in ST4 .

Vehicle 2 Car, travelling from SE to NW was stopping on the main carriageway. The vehicle was approaching junction or waiting/parked at junction approach and collided with vehicle 1.
The female driver aged 34 lived in ST10 had regularly travelled through the site before.

Vehicle 3 Car, travelling from SE to NW was stopping on the main carriageway. The vehicle was approaching junction or waiting/parked at junction approach and collided with vehicle 2. The male driver aged 55.

Vehicle 4 Other motor vehicle, travelling from SW to SE was turning right on the main carriageway. The vehicle was entering main road. The male driver aged 40.

Casualty 1 (Vehicle 2) A female driver aged 34 suffered a slight injury.

Contributory Factors

Vehicle 1 Vegetation
Vehicle 1 Failed to look properly

Acc. Ref. No:	08013040	Road:	A 50	Grid Reference:	396390	340530
District Council:	Staffordshire Moorland	Time:	0624		Tuesday	01-July-2008
Lighting:	Daylight:street lights present	Weather:	Fine without high winds	Speed limit:	70	
Severity:	SLIGHT	Road surface	Dry			
Location:	DRAYCOTT R'BOUT STONEHOUSES J/W A50 S/BOUND					

The accident occurred at a roundabout on the A50, at its junction with the A50 controlled by a give way or uncontrolled..

Special conditions and hazards: None

Vehicle 1 Goods 7.5 tonnes mgw and over, travelling from W to W was performing a U-turn on the main carriageway. The vehicle was mid junction - on roundabout or main road and collided with vehicle 2.
The male driver aged 41 had not travelled through the site before.

Vehicle 2 Car, travelling from W to SE was turning right on the main carriageway. The vehicle was leaving roundabout and collided with vehicle 1. The male driver aged 36 lived in ST6 had regularly travelled through the site before.

Casualty 1 (Vehicle 2) A male vehicle or pillion passenger aged 35 suffered a slight injury.

Contributory Factors

Vehicle 1 Failed to judge other persons path or speed

Acc. Ref. No:	08017805	Road:	A 521	Grid Reference:	396720	340720
District Council:	Staffordshire Moorland	Time:	1835		Tuesday	25-November-2008
Lighting:	Darkness: street lights present and lit	Weather:	Fine without high winds	Speed limit:	70	
Severity:	SLIGHT	Road surface	Wet/Damp			
Location:	UTTOXETERRD. J/W UTTOXETER RD. BLYTHE BRIDGE.					

The accident occurred at a T or staggered junction on the A521, a dual carriageway at its junction with the A521 controlled by a give way or uncontrolled..

Special conditions and hazards: None

Vehicle 1 Car, travelling from NW to NE was turning left on the main carriageway. The vehicle was leaving main road and collided with vehicle 2. The male driver aged 38 lived in ST11 had regularly travelled through the site before.

Vehicle 2 Car, travelling from SW to N was going ahead on a right bend on the main carriageway. The vehicle was mid junction - on roundabout or main road and collided with vehicle 1.
The male driver aged 28 lived in ST15 had regularly travelled through the site before.

Casualty 1 (Vehicle 1) A male driver aged 38 suffered a slight injury.

Contributory Factors

Vehicle 1 Junction overshoot
Vehicle 1 Junction restart
Vehicle 1 Failed to look properly

AccsMap - Accident Analysis Syster
Accidents between dates **01/05/2007 and 30/04/2012** (60) months

Selection:
Notes:

Selected using Manual Selection

Acc. Ref. No:	09004311	Road:	C 109	Grid Reference:	397430 340420
District Council:	Staffordshire Moorland	Time:	1648		Saturday 30-May-2009
Lighting:	Daylight:street lights present	Weather:	Fine without high winds	Speed limit:	40
Severity:	SLIGHT	Road surface	Dry		
Location:	UTTOXETER ROAD APPROX 150 MTS EAST OF NEW AVE DRAYCOTT				

The accident occurred on the C109, a single carriageway .

Special conditions and hazards: None

Vehicle 1 Car, travelling from NW to SE was stopping on the main carriageway. The vehicle was not at, or within 20M of a junction. The male driver aged 47 lived in ST11 had regularly travelled through the site before.

Vehicle 2 Car, travelling from NW to SE was changing lane to right on the main carriageway. The vehicle was not at, or within 20M of a junction and collided with vehicle 3. The male driver aged 18 lived in ST11 had occasionally travelled through the site before.

Vehicle 3 Car, travelling from SE to NW was going ahead other on the main carriageway. The vehicle was not at, or within 20M of a junction and collided with vehicle 2. The female driver aged 47 lived in ST3 .

Casualty 1 (Vehicle 3) A female vehicle or pillion passenger aged 17 suffered a slight injury.

Casualty 2 (Vehicle 3) A female vehicle or pillion passenger aged 21 suffered a slight injury.

Contributory Factors

Vehicle 2 Inexperienced or learner driver/rider

Vehicle 2 Aggressive driving

Vehicle 1 Aggressive driving

Vehicle 2 Swerved

Acc. Ref. No:	09005692	Road:	A 50	Grid Reference:	396370 340570
District Council:	Staffordshire Moorland	Time:	1215		Monday 20-July-2009
Lighting:	Daylight:street lights present	Weather:	Fine without high winds	Speed limit:	60
Severity:	SLIGHT	Road surface	Dry		
Location:	BLYTHE BRIDGE R'BT J/W UTTOXETER RD SOT				

The accident occurred at a roundabout on the A50, at its junction with the A521 controlled by a give way or uncontrolled..

Special conditions and hazards: None

Vehicle 1 Car, travelling from W to NE was changing lane to left on the main carriageway. The vehicle was leaving roundabout and collided with vehicle 2. The male driver aged 52 lived in LE10 had not travelled through the site before.

Vehicle 2 Goods 7.5 tonnes mgw and over, travelling from W to NE was turning left on the main carriageway. The vehicle was leaving roundabout and collided with vehicle 1. The male driver aged 31.

Casualty 1 (Vehicle 2) A female vehicle or pillion passenger aged 50 suffered a slight injury.

Casualty 2 (Vehicle 2) A female vehicle or pillion passenger aged 1 suffered a slight injury.

Casualty 3 (Vehicle 2) A female vehicle or pillion passenger aged 3 suffered a slight injury.

Casualty 4 (Vehicle 1) A male driver aged 52 suffered a slight injury.

Contributory Factors

Vehicle 1 Poor turn or manoeuvre

Vehicle 1 Failed to look properly

Vehicle 1 Distraction in vehicle

Vehicle 1 Careless/Reckless/In a hurry

Acc. Ref. No:	09006950	Road:	C 13	Grid Reference:	397540 339320
District Council:	Staffordshire Moorland	Time:	0015		Wednesday 02-September-2009
Lighting:	Darkness: street lights present and lit	Weather:	Fine without high winds	Speed limit:	30
Severity:	SLIGHT	Road surface	Dry		
Location:	CRESSWELL LN.ON RAILWAY CROSSING NEAR CRESSWELL OLD LN.				

The accident occurred at a T or staggered junction on the C13, a single carriageway at its junction with the Unclassified172 controlled by a give way or uncontrolled..

Special conditions and hazards: None

Vehicle 1 Car, travelling from SW to NE was going ahead other on the main carriageway. The vehicle was approaching junction or waiting/parked at junction approach. The male driver aged 26 lived in ST13 had occasionally travelled through the site before.

Casualty 1 (Vehicle 1) A male driver aged 26 suffered a slight injury.

Casualty 2 (Vehicle 1) A female vehicle or pillion passenger aged 16 suffered a slight injury.

Contributory Factors

Vehicle 1 Loss of control

Vehicle 1 Aggressive driving

AccsMap - Accident Analysis Syster
Accidents between dates **01/05/2007 and 30/04/2012** (60) months

Selection:

Selected using Manual Selection

Notes:

Acc. Ref. No:	09008175	Road:	C 13	Grid Reference:	397670	339480
District Council:	Staffordshire Moorland	Time:	1340	Wednesday	28-October-2009	
Lighting:	Daylight: no street lighting	Weather:	Fine without high winds		Speed limit:	60
Severity:	SLIGHT	Road surface	Dry			
Location:	CRESSWELL LANE BETWEEN WALTON HOUSE & BLYTHE CRICKET CLUB					

The accident occurred on the C13, a single carriageway .

Special conditions and hazards: None

Vehicle 1 Car, travelling from SW to NE was going ahead other on the main carriageway. The vehicle was not at, or within 20M of a junction and collided with vehicle 2. The female driver aged 31 lived in ST10.

Vehicle 2 Goods 3.5 tonnes mgw and under, travelling from NE to SW was going ahead other on the main carriageway. The vehicle was not at, or within 20M of a junction and collided with vehicle 1. The male driver aged 43 lived in SY4 .

Casualty 1 (Vehicle 1) A female driver aged 31 suffered a slight injury.

Contributory Factors

Vehicle 1 Loss of control

Vehicle 1 Distraction in vehicle

Acc. Ref. No:	10003166	Road:	A 50	Grid Reference:	396390	340530
District Council:	Staffordshire Moorland	Time:	1155	Monday	17-May-2010	
Lighting:	Daylight:street lights present	Weather:	Fine without high winds		Speed limit:	60
Severity:	SLIGHT	Road surface	Dry			
Location:	A50 E/B BLYTHE BRIDGE J/W DRAYCOTT ISLAND					

The accident occurred at a roundabout on the A50, at its junction with the A521 controlled by a give way or uncontrolled..

Special conditions and hazards: None

Vehicle 1 Goods 7.5 tonnes mgw and over, travelling from SW to SE was turning right on the main carriageway. The vehicle was leaving roundabout. The male driver aged 43 lived in M34 .

Casualty 1 (Vehicle 1) A male driver aged 43 suffered a slight injury.

Contributory Factors

Vehicle 1 Poor or defective road surface

Vehicle 1 Overloaded or poorly loaded vehicle or trailer

Vehicle 1 Loss of control

Acc. Ref. No:	10003951	Road:	C 109	Grid Reference:	398012	340162
District Council:	Staffordshire Moorland	Time:	0850	Wednesday	23-June-2010	
Lighting:	Daylight:street lights present	Weather:	Fine without high winds		Speed limit:	40
Severity:	SERIOUS	Road surface	Dry			
Location:	UTTOXETER RD J/W CRESSWELL LANE DRAYCOTT					

The accident occurred at a T or staggered junction on the C109, a single carriageway at its junction with the C13 controlled by a give way or uncontrolled..

Special conditions and hazards: None

Vehicle 1 Car, travelling from NW to SW was turning right on the main carriageway. The vehicle was leaving main road and collided with vehicle 2. The male driver aged 69 lived in ST11 had regularly travelled through the site before.

Vehicle 2 Motor Cycle over 50 cc and up to 125cc, travelling from SE to NW was going ahead other on the main carriageway. The vehicle was mid junction - on roundabout or main road and collided with vehicle 1. The male driver aged 26 lived in ST3 had regularly travelled through the site before.

Casualty 1 (Vehicle 1) A male driver aged 69 suffered a slight injury.

Casualty 2 (Vehicle 2) A male rider aged 26 suffered a serious injury.

Contributory Factors

Vehicle 1 Failed to look properly

Vehicle 1 Careless/Reckless/In a hurry

AccsMap - Accident Analysis Syster
Accidents between dates **01/05/2007 and 30/04/2012** (60) months

Selection:

Selected using Manual Selection

Notes:

Acc. Ref. No:	10004298	Road:	A 521	Grid Reference:	396697	340719
District Council:	Staffordshire Moorland	Time:	1150	Friday	09-July-2010	
Lighting:	Daylight:street lights present	Weather:	Fine without high winds			Speed limit: 70
Severity:	SLIGHT	Road surface	Dry			
Location:	UTTOXETER RD.BLYTHE BRIDGE J/W UTTOXETER					

The accident occurred at a T or staggered junction on the A521, a dual carriageway at its junction with the A521 controlled by a give way or uncontrolled..

Special conditions and hazards: None

Vehicle 1 Car, travelling from E to N was turning right on the main carriageway. The vehicle was entering main road and collided with vehicle 2. The female driver aged 32 lived in ST5 had regularly travelled through the site before.

Vehicle 2 Car, travelling from SW to E was going ahead other on the main carriageway. The vehicle was mid junction - on roundabout or main road and collided with vehicle 1. The female driver aged 58 lived in ST10 had regularly travelled through the site before.

Casualty 1 (Vehicle 2) A female driver aged 58 suffered a slight injury.

Contributory Factors

Vehicle 1 Failed to look properly

Acc. Ref. No:	10005273	Road:	C 109	Grid Reference:	397126	340555
District Council:	Staffordshire Moorland	Time:	0750	Tuesday	24-August-2010	
Lighting:	Daylight:street lights present	Weather:	Fine without high winds			Speed limit: 40
Severity:	SLIGHT	Road surface	Dry			
Location:	UTTOXETER RD O/S NO.46 DRAYCOTT IN THE MOORS					

The accident occurred at a private drive on the C109, a single carriageway controlled by a give way or uncontrolled..

Special conditions and hazards: None

Vehicle 1 Car, travelling from SE to NW was going ahead but held up on the main carriageway. The vehicle was approaching junction or waiting/parked at junction approach and collided with vehicle 2.

The female driver aged 50 lived in ST11 had regularly travelled through the site before.

Vehicle 2 Goods 3.5 tonnes mgw and under, travelling from SE to NW was going ahead but held up on the main carriageway. The vehicle was approaching junction or waiting/parked at junction approach and collided with vehicle 3.

The male driver aged 54 lived in ST11 had regularly travelled through the site before.

Vehicle 3 Goods over 3.5 tonnes and under 7.5 tonnes mgw, travelling from SE to NW was stopping on the main carriageway. The vehicle was approaching junction or waiting/parked at junction approach and collided with vehicle 2.

The male driver aged 63 lived in ST3 had regularly travelled through the site before.

Vehicle 4 Goods 7.5 tonnes mgw and over, travelling from NW to SW was reversing on the main carriageway. The vehicle was leaving main road. The male driver aged 45.

Casualty 1 (Vehicle 1) A female driver aged 50 suffered a slight injury.

Contributory Factors

Vehicle 2 Sudden braking

Vehicle 1 Sudden braking

Vehicle 3 Loss of control

Vehicle 3 Failed to judge other persons path or speed

Acc. Ref. No:	10005328	Road:	C 109	Grid Reference:	398163	340099
District Council:	Staffordshire Moorland	Time:	1010	Tuesday	31-August-2010	
Lighting:	Daylight:street lights present	Weather:	Fine without high winds			Speed limit: 40
Severity:	SLIGHT	Road surface	Dry			
Location:	UTTOXETER RD.J/W ENT.MANOR FARM DRAYCOTT.					

The accident occurred at a private drive on the C109, a single carriageway controlled by a give way or uncontrolled..

Special conditions and hazards: None

Vehicle 1 Car, travelling from NW to SE was going ahead other on the main carriageway. The vehicle was approaching junction or waiting/parked at junction approach and collided with vehicle 2.

The male driver aged 85 lived in ST3 had regularly travelled through the site before.

Vehicle 2 Agricultural vehicle, travelling from NW to SW was turning right on the main carriageway. The vehicle was leaving main road and collided with vehicle 1. The male driver aged 24 lived in ST11 had regularly travelled through the site before.

Casualty 1 (Vehicle 1) A male driver aged 85 suffered a slight injury.

Contributory Factors

Vehicle 1 Failed to judge other persons path or speed

Vehicle 1 Careless/Reckless/In a hurry

Vehicle 2 Defective lights or indicators

AccsMap - Accident Analysis Syster
Accidents between dates **01/05/2007 and 30/04/2012** (60) months

Selection:

Selected using Manual Selection

Notes:

Acc. Ref. No:	11001885	Road:	C 109	Grid Reference:	398029	340160
District Council:	Staffordshire Moorland	Time:	1955		Saturday	02-April-2011
Lighting:	Darkness: street lights present and lit	Weather:	Fine without high winds	Speed limit:	40	
Severity:	SLIGHT	Road surface	Dry			
Location:	UTTOXETER RD DRAYCOTT J/W CRESSWELL LANE					

The accident occurred at a T or staggered junction on the C109, a single carriageway at its junction with the C13 controlled by a give way or uncontrolled..

Special conditions and hazards: None

Vehicle 1 Car, travelling from NW to SE was overtaking a moving vehicle on the offside on the main carriageway. The vehicle was approaching junction or waiting/parked at junction approach and collided with vehicle 003.
The male driver aged 22 lived in ST10 had regularly travelled through the site before.

Vehicle 2 Car, travelling from NW to SE was going ahead other on the main carriageway. The vehicle was approaching junction or waiting/parked at junction approach and collided with vehicle 001.
The female driver aged 64 lived in CW11 had regularly travelled through the site before.

Vehicle 3 Car, travelling from SW to SE was turning right on the main carriageway. The vehicle was mid junction - on roundabout or main road and collided with vehicle 001. The female driver aged 19 lived in ST16 had regularly travelled through the site before.

Casualty 1 (Vehicle 1) A male driver aged 22 suffered a slight injury.

Contributory Factors

Vehicle 1 Exceeding speed limit
Vehicle 3 Failed to judge other persons path or speed

Acc. Ref. No:	11002772	Road:	A 50	Grid Reference:	396366	340566
District Council:	Staffordshire Moorland	Time:	1128		Sunday	15-May-2011
Lighting:	Daylight:street lights present	Weather:	Raining without high winds	Speed limit:	50	
Severity:	SLIGHT	Road surface	Wet/Damp			
Location:	BLYTHE BRIDGE R/B A50 J/W A521					

The accident occurred at a roundabout on the A50, at its junction with the A521 controlled by a give way or uncontrolled..

Special conditions and hazards: None

Vehicle 1 Car, travelling from SW to NE was going ahead other on the main carriageway. The vehicle was leaving roundabout and overturned and collided with vehicle 2. The female driver aged 31 lived in ST10.

Vehicle 2 Car, travelling from SW to SE was turning right on the main carriageway. The vehicle was mid junction - on roundabout or main road and collided with vehicle 1. The male driver aged 27 lived in ST15.

Casualty 1 (Vehicle 1) A female driver aged 31 suffered a slight injury.

Contributory Factors

Vehicle 1 Failed to look properly

Acc. Ref. No:	11004999	Road:	A 50	Grid Reference:	396347	340519
District Council:	Staffordshire Moorland	Time:	2055		Saturday	10-September-2011
Lighting:	Darkness: street lights present and lit	Weather:	Fine without high winds	Speed limit:	70	
Severity:	SLIGHT	Road surface	Wet/Damp			
Location:	A50 DRAYCOTT R'BT J/W A521					

The accident occurred at a roundabout on the A50, at its junction with the A521 controlled by a give way or uncontrolled..

Special conditions and hazards: None

Vehicle 1 Motorcycle over 500cc, travelling from SE to W was turning left on the main carriageway. The vehicle was leaving roundabout and collided with vehicle 2. The male driver aged 41 lived in DH8 had occasionally travelled through the site before.

Vehicle 2 Car, travelling from SE to NE was turning right on the main carriageway. The vehicle was mid junction - on roundabout or main road and collided with vehicle 1. The female driver aged 54 lived in ST11 had regularly travelled through the site before.

Casualty 1 (Vehicle 1) A male rider aged 41 suffered a slight injury.

Contributory Factors

Vehicle 1 Failed to look properly
Vehicle 1 Failed to judge other persons path or speed
Vehicle 2 Failed to signal/Misleading signal

AccsMap - Accident Analysis Syster
Accidents between dates **01/05/2007 and 30/04/2012** (60) months

Selection:

Selected using Manual Selection

Notes:

Acc. Ref. No:	11005904	Road:	A 51	Grid Reference:	396390	340554
District Council:	Staffordshire Moorland	Time:	1118		Friday	21-October-2011
Lighting:	Daylight: street lighting unknown	Weather:	Fine without high winds	Speed limit:	50	
Severity:	SLIGHT	Road surface	Dry			
Location:	A50 ROUNDABOUT J/W UTTOXETER RD BLYTHE BRIDGE					

The accident occurred at a roundabout on the A51, at its junction with the A521 controlled by a give way or uncontrolled..

Special conditions and hazards: Dislodged vehicle load in carriageway

Vehicle 1 Goods 7.5 tonnes mgw and over, travelling from W to S was turning right on the main carriageway. The vehicle was mid junction - on roundabout or main road. The male driver aged 23 lived in CA3 .

Vehicle 2 Car, travelling from NE to SW was going ahead other on the main carriageway. The vehicle was approaching junction or waiting/parked at junction approach. The female driver aged 73 lived in ST5 .

Casualty 1 (Vehicle 2) A female driver aged 73 suffered a slight injury.

Contributory Factors

Vehicle 1 Overloaded or poorly loaded vehicle or trailer

Acc. Ref. No:	11006819	Road:	C 13	Grid Reference:	397557	339337
District Council:	Staffordshire Moorland	Time:	1737		Wednesday	07-December-2011
Lighting:	Darkness: street lights present and lit	Weather:	Fine without high winds	Speed limit:	40	
Severity:	SLIGHT	Road surface	Wet/Damp			
Location:	CRESWELL LANE J/W CRESWELL OLD LANE CRESWELL					

The accident occurred at a crossroads on the C13, a single carriageway at its junction with the Unclassified172 controlled by a give way or uncontrolled..

Special conditions and hazards: None

Vehicle 1 Car, travelling from SE to NW was going ahead other on the main carriageway. The vehicle was entering main road and collided with vehicle 2. The female driver aged 45 lived in ST11.

Vehicle 2 Car, travelling from SW to NE was going ahead other on the main carriageway. The vehicle was mid junction - on roundabout or main road and collided with vehicle 1. The female driver aged 47 lived in ST11 had regularly travelled through the site before.

Casualty 1 (Vehicle 2) A male vehicle or pillion passenger aged 12 suffered a slight injury.

Casualty 2 (Vehicle 2) A female driver aged 47 suffered a slight injury.

Contributory Factors

Vehicle 1 Failed to look properly

Vehicle 1 Failed to judge other persons path or speed

Acc. Ref. No:	12000214	Road:	A 50	Grid Reference:	396373	340504
District Council:	Staffordshire Moorland	Time:	1730		Saturday	07-January-2012
Lighting:	Darkness: street lights present and lit	Weather:	Fine with high winds	Speed limit:	50	
Severity:	SLIGHT	Road surface	Dry			
Location:	A50 R'BT APPROX 13MTS SOUTH J/W UTTOXETER RD BLYTHE BRIDGE					

The accident occurred at a roundabout on the A50, at its junction with the A521 controlled by a give way or uncontrolled..

Special conditions and hazards: Any animal in carriageway (except ridden horse)

Vehicle 1 Motorcycle over 500cc, travelling from SE to SW was turning left on the main carriageway. The vehicle was entering roundabout and skidded. The male driver aged 51 lived in CW2 .

Casualty 1 (Vehicle 1) A male rider aged 51 suffered a slight injury.

Contributory Factors

Vehicle 1 Deposit on road (eg oil, mud, chippings)

AccsMap - Accident Analysis System
Accidents between dates **01/05/2007 and 30/04/2012** (60) months

Selection:
Notes:

Selected using Manual Selection

Acc. Ref. No:	12000692	Road:	A 50	Grid Reference:	396382 340551
District Council:	Staffordshire Moorland	Time:	2050		Friday
Lighting:	Darkness: street lights present and lit	Weather:	Fine without high winds		03-February-2012
Severity:	SLIGHT	Road surface	Dry	Speed limit:	60
Location:	A50 BLYTHE BRIDGE BYPASS J/W UTTOXETER RD R'BT BLYTHE BRIDGE				

The accident occurred at a roundabout on the A50, at its junction with the A521 controlled by a give way or uncontrolled..

Special conditions and hazards: None

Vehicle 1 Car, travelling from NE to SW was going ahead other on the main carriageway. The vehicle was entering roundabout. The male driver aged 19 lived in ST5 had regularly travelled through the site before.

Casualty 1 (Vehicle 1) A male vehicle or pillion passenger aged 19 suffered a slight injury.

Casualty 2 (Vehicle 1) A male vehicle or pillion passenger aged 26 suffered a slight injury.

Contributory Factors

Vehicle 1	Loss of control
Vehicle 1	Impaired by alcohol
Vehicle 1	Aggressive driving

Accidents between dates **01/05/2012 and 30/09/2013** (17) months

Selection: _____ **Notes:** _____

Selected using Manual Selection

Acc. Ref. No:	12002851	Road:	A 521	Grid Reference:	396693	340744
District Council:	Staffordshire Moorland	Time:	1835	Monday	04-June-2012	
Lighting:	Daylight:street lights present	Weather:	Fine without high winds			Speed limit: 30
Severity:	SLIGHT	Road surface	Wet/Damp			

The accident occurred at a T or staggered junction on the A521, a single carriageway at its junction with the A521 controlled by a give way or uncontrolled..

Special conditions and hazards: None

Vehicle 1	Car, travelling from SW to NW was turning left on the main carriageway. The vehicle was entering main road. The male driver aged 33 lived in ST1 had occasionally travelled through the site before.
------------------	--

Casualty 1 (Vehicle 1) A male driver aged 33 suffered a slight injury.

Contributory Factors

Vehicle 1	Other
-----------	-------

Acc. Ref. No:	12004549	Road:	C 13	Grid Reference:	397902	339920	
District Council:	Staffordshire Moorland	Time:	1200	Friday	31-August-2012		
Lighting:	Daylight:street lights present	Weather:	Fine without high winds			Speed limit:	30
Severity:	SLIGHT	Road surface	Dry				
Location:	CRESSWELL LANE DRAYCOTT IN THE MOORS O/S DRAYCOTT SPORTS CENTRE						

The accident occurred on the C13, a single carriageway.

Special conditions and hazards: None

Vehicle 1 Car, travelling from SW to NE was going ahead other on the main carriageway. The vehicle was not at, or within 20M of a junction and collided with vehicle 2. The male driver aged 29 lived in ST15.

Vehicle 2 Car, travelling from NE to SW was going ahead other on the main carriageway. The vehicle was not at, or within 20M of a junction and collided with vehicle 1. The male driver aged 47 lived in ST3 .

Casualty 1 (Vehicle 2) A male driver aged 47 suffered a slight injury.

Casualty 2	(Vehicle 2)	A female vehicle or pillion passenger aged 52 suffered a slight injury.
-------------------	-------------	---

Contributory Factors

Vehicle 1 Swerved

Vehicle 1	Loss of control
-----------	-----------------

Acc. Ref. No:	12005515	Road:	C 109	Grid Reference:	397419	340425	
District Council:	Staffordshire Moorland	Time:	1750	Tuesday	16-October-2012		
Lighting:	Daylight:street lights present	Weather:	Fine without high winds			Speed limit:	40
Severity:	SLIGHT	Road surface	Dry				
Location:	UTTOXETER RD DRAYCOTT O/S NO.145						

The accident occurred on the C109, a single carriageway.

Special conditions and hazards: None

Vehicle 1 Car, travelling from NW to SE was going ahead other on the main carriageway. The vehicle was not at, or within 20M of a junction and collided with vehicle 2. The female driver aged 56 lived in ST10 had regularly travelled through the site before.

Vehicle 2 Car, travelling from NW to SE on the main carriageway. The vehicle was not at, or within 20M of a junction and collided with vehicle 1. The male driver aged 22 lived in ST11.

Casualty 1 (Vehicle 1) A female driver aged 56 suffered a slight injury.

Contributory Factors

Vehicle 1 Failed to look properly

Accidents between dates **01/05/2012 and 30/09/2013** (17) months

Selection: _____ **Notes:** _____

Selected using Manual Selection

Acc. Ref. No:	12005733	Road:	A 521	Grid Reference:	396395	340557	
District Council:	Staffordshire Moorland	Time:	1505	Friday	26-October-2012		
Lighting:	Daylight:street lights present	Weather:	Fine without high winds			Speed limit:	30
Severity:	SLIGHT	Road surface	Dry				
Location:	A521 BLYTHE BRIDGE APPROX 5 MTRAS N/E OF J/W A50 R'BOUT						

The accident occurred at a roundabout on the A521, at its junction with the A50 controlled by a give way or uncontrolled..

Special conditions and hazards: None

Vehicle 1	Goods 7.5 tonnes mgw and over, travelling from NE to SW was overtaking a static vehicle on the offside on the main carriageway. The vehicle was approaching junction or waiting/parked at junction approach and collided with vehicle 2.
------------------	--

Vehicle 2 The untraced driver of an unknown age .
Car, travelling from NE to SW was going ahead but held up on the main carriageway. The vehicle was approaching junction or waiting/parked at junction approach and collided with vehicle 1.

Vehicle 3 The female driver aged 29 lived in ST3 had regularly travelled through the site before. Goods over 3.5 tonnes and under 7.5 tonnes mgw, travelling from S to E was going ahead other on the main carriageway. The vehicle was mid junction - on roundabout or main road. The male driver of an unknown age.

Casualty 1 (Vehicle 2) A female driver aged 29 suffered a slight injury.

Contributory Factors

Vehicle 1	Poor turn or manoeuvre
Vehicle 1	Failed to judge other persons path or speed
Vehicle 1	Swerved
Vehicle 1	Careless/Reckless/In a hurry

Acc. Ref. No:	13001186	Road:	C 109	Grid Reference:	397347	340459	
District Council:	Staffordshire Moorland	Time:	0830	Tuesday	26-February-2013		
Lighting:	Daylight	Weather:	Fine without high winds			Speed limit:	40
Severity:	SLIGHT	Road surface	Dry				
Location:	UTTOXETER RD DRAYCOTT O/S NO.127						

The accident occurred on the C109, a single carriageway.

Special conditions and hazards: None

Vehicle 1 Car, travelling from NW to SE was going ahead other on the main carriageway. The vehicle was not at, or within 20M of a junction. The female driver aged 42 lived in ST3 had regularly travelled through the site before.

Vehicle 2 Car, on the main carriageway. The vehicle was not at, or within 20M of a junction. The male driver aged 71 had regularly travelled through the site before.

Casualty 1 (Vehicle 1) A female driver aged 42 suffered a slight injury.

Contributory Factors

Vehicle 1	Distraction outside vehicle
Vehicle 1	Careless/Reckless/In a hurry

Acc. Ref. No:	13002197	Road:	C 109	Grid Reference:	397385	340440	
District Council:	Staffordshire Moorland	Time:	1215	Thursday	25-April-2013		
Lighting:	Daylight	Weather:	Fine without high winds			Speed limit:	40
Severity:	SLIGHT	Road surface	Dry				
Location:	UTTOXETER RD OPP NO.106 DRAYCOTT IN THE MOORS						

The accident occurred on the C109, a single carriageway.

Special conditions and hazards: None

Vehicle 1 Van or Goods 3.5 tonnes mgw and under, travelling from SE to SE was performing a U-turn on the main carriageway. The vehicle was not at, or within 20M of a junction. The male driver aged 78 lived in ST6 .

Vehicle 2 Goods 7.5 tonnes mgw and over, travelling from NW to SE was going ahead other on the main carriageway. The vehicle was not at, or within 20M of a junction. The male driver aged 48 lived in ST10 had regularly travelled through the site before.

Casualty 1 (Vehicle 1) A male driver aged 78 suffered a slight injury.

Contributory Factors

Vehicle 1	Illegal turn or direction of travel
Vehicle 1	Poor turn or manoeuvre
Vehicle 1	Failed to look properly
Vehicle 1	Failed to judge other persons path or speed

AccsMap - Accident Analysis System

Accidents between dates **01/05/2012 and 30/09/2013** (17) months

Selection: _____ **Notes:** _____

Selected using Manual Selection

Acc. Ref. No:	13002998	Road:	C 109	Grid Reference:	398013	340164	
District Council:	Staffordshire Moorland	Time:	1710	Thursday	06-June-2013		
Lighting:	Daylight	Weather:	Fine without high winds			Speed limit:	40
Severity:	SLIGHT	Road surface	Dry				
Location:	UTTOXETER RD DRAYCOTT IN THE MOORS J/W CRESSWELL LANE						

The accident occurred at a T or staggered junction on the C109, a single carriageway at its junction with the C13 controlled by a give way or uncontrolled..

Special conditions and hazards: None

Vehicle 1	Car, travelling from SW to SE was turning right on the main carriageway. The vehicle was entering main road. The female driver aged 28 lived in ST10 had regularly travelled through the site before.
------------------	---

Vehicle 2 Motorcycle over 500cc, travelling from SE to NW was going ahead other on the main carriageway. The vehicle was mid junction - on roundabout or main road. The male driver aged 31 lived in ST11.

Vehicle 3 Car, was turning left on the main carriageway. The vehicle was leaving main road. The untraced driver of an unknown age .

Casualty 1 (Vehicle 2) A male rider aged 31 suffered a slight injury.

Contributory Factors

Vehicle 1 Failed to look properly

Acc. Ref. No:	13002946	Road:	A 50	Grid Reference:	396464	340384	
District Council:	Staffordshire Moorland	Time:	1645	Thursday	06-June-2013		
Lighting:	Daylight	Weather:	Fine without high winds			Speed limit:	70
Severity:	SLIGHT	Road surface	Dry				
Location:	A50 W/B BLYTHE BRIDGE APPROX 160MTS SE R/BT J/W UTTOXETER RD						

The accident occurred on the A50, a dual carriageway.

Special conditions and hazards: None

Vehicle 1	Car, travelling from SE to N was going ahead on a right bend on the main carriageway. The vehicle was not at, or within 20M of a junction. The female driver aged 30 lived in CW11 had occasionally travelled through the site before.
------------------	--

Vehicle 2 Car, was stopping on the main carriageway. The vehicle was not at, or within 20M of a junction. The female driver aged 40 lived in ST14 had regularly travelled through the site before.

Vehicle 3 Car, travelling from SE to N was stopping on the main carriageway. The vehicle was not at, or within 20M of a junction. The female driver aged 43 lived in L31 had occasionally travelled through the site before.

Casualty 1 (Vehicle 1) A female driver aged 30 suffered a slight injury.

Casualty 2 (Vehicle 2) A female driver aged 40 suffered a slight injury.

Contributory Factors

Vehicle 1 Failed to judge other persons path or speed

Vehicle 2	Failed to judge other persons path or speed
-----------	---

Acc. Ref. No:	13003540	Road:	A 521	Grid Reference:	396696	340719	
District Council:	Staffordshire Moorland	Time:	1040	Sunday	07-July-2013		
Lighting:	Daylight	Weather:	Fine without high winds			Speed limit:	70
Severity:	SLIGHT	Road surface	Dry				
Location:	UTTOXETER RD BLYTHE BRIDGE J/W UTTOXETER RD						

The accident occurred at a T or staggered junction on the A521, a dual carriageway at its junction with the A521 controlled by a give way or uncontrolled..

Special conditions and hazards: None

Vehicle 1 Car, travelling from E to NW was turning right on the main carriageway. The vehicle was leaving main road. The female driver aged 70 lived in NN10 had not travelled through the site before.

Vehicle 2 Road in NW16 had not travelled through the site before. Car, travelling from SW to E was going ahead on a right bend on the main carriageway. The vehicle was mid junction - on roundabout or main road. The female driver aged 32 lived in ST4 .

Casualty 1 (Vehicle 1) A female driver aged 70 suffered a slight injury.

Casualty 2 (Vehicle 2) A female driver aged 32 suffered a slight injury.

Contributory Factors

Vehicle 1	Road layout (eg bend, hill etc.)

Vehicle 1	Failed to look properly
-----------	-------------------------

Vehicle 1 Vegetation

Accidents between dates **01/05/2012 and 30/09/2013** (17) months

Selection: _____ **Notes:** _____

Selected using Manual Selection

Acc. Ref. No:	13005067	Road:	A 50	Grid Reference:	396303	340539	
District Council:	Staffordshire Moorland	Time:	1650	Thursday	26-September-2013		
Lighting:	Daylight	Weather:	Fine without high winds			Speed limit:	50
Severity:	SLIGHT	Road surface	Dry				
Location:	A50 E/B ON APPROACH TO BLYTHE BRIDGE R'BOUT ADJOINING A521						

The accident occurred on the A50, a dual carriageway.

Special conditions and hazards: None

Vehicle 1	Car, travelling from SW to NE was stopping on the main carriageway. The vehicle was not at, or within 20M of a junction. The male driver aged 32 lived in ST4 .
------------------	---

Vehicle 2 Car, travelling from SW to NE was going ahead other on the main carriageway. The vehicle was not at, or within 20M of a junction. The male driver aged 38 lived in ST11 had regularly travelled through the site before.

Casualty 1 (Vehicle 1) A male driver aged 32 suffered a slight injury.

Casualty 2 (Vehicle 2) A male driver aged 38 suffered a slight injury.

Contributory Factors

Vehicle 1	Other
-----------	-------