

MANHOLE DETAIL A -
SITED IN HARD LANDSCAPED AREAS
SUBJECT TO LIGHT VEHICLE LOADING



MANHOLE DETAIL B -
SITED IN SOFT LANDSCAPED AREAS



MANHOLE DETAIL C -
SITED IN HARD LANDSCAPED AREAS
SUBJECT TO VEHICLE LOADING



PIPEWORK PASSING UNDER EXISTING FOOTING





Pipe dia.	Rocker pipe length.
150 - 450	500 - 750
451 - 751	750 - 1000
751+	seek guidence

PCC MANHOLE DETAIL



DETAIL OF EXPANSION JOINTS FOR CONCRETE BED OR SURROUND





BRICK MANHOLE DETAIL



PIPEWORK PASSING THROUGH UNDERPINNING



PLAN ON INSPECTION CHAMBER





RE - RODDING EYE DETAIL

Rev ID	Date	Comment
	03/05/2016	

wood | goldstraw | yorath
ARCHITECTS QUANTITY SURVEYORS CDM CO-ORDINATORS
Churchill House, Regent Road, Stoke on Trent, ST1 3RH.
Tel: 01782 208000 Fax: 01782 208712 E-mail: info@woodgoldstraw.co.uk
www.woodgoldstraw.co.uk

Client.
Faber RC Primary School, Cotton

Project.
New Classroom & Dining Room

Scale	Issue Date
1:20	06/05/2016
Sheet Size: A1	Drawn:

Title.
Drainage Details

Drawing Number	/ (Revision)	Revison ID
3142-10-30		

CAD file path:
X:\1 A CAPPER'S TEAM\1 RC SCHOOL\COTTON - FABER RCS\3142-10 FOUNDATION UNIT\3142-10 Tender 2.pln