Sunny Bank Longsdon Bat EPS Licence Application July 2016

C4 Photographs of Survey Areas

Plate 1: Building 1a (“Inhabited cottage”) and Building 1b (“unconverted ‘barn”) showing existing south-east aspect of building (Taken 10.09.15)



Plate 2: Showing north-west side of roof and north gable end of Building 1b. View of surveyor No.2 during dusk and dawn surveys (Taken 10.09.15).



Plate 3: Building 1b showing roost locations and possible access points on south-east side of building and inside (Taken 10.09.15).



Plate 4: Building 1b – showing location of crevice roost under door stone lintel and view into existing roof space of Building 1a (Taken 10.09.15).



Plate 5: Stone wall inside Building 1b which separates Building 1a from 1b showing opening into cottage roof space (left) and crevices in wall (right) (Taken 10.09.15).

