
Specifications for mitigation and enhancement	
Figure reference:	**FIGURE E3**
Structure:	Cresswell Ford Farm
Address:	Dilhorne Lane Dilhorne Staffordshire Moorlands ST10 2PH
National GR:	SJ961429
Date:	SEPTEMBER 2019

Brown long-eared bat



West elevation

September 2019




North elevation

September 2019

Ridge tile access gaps to be 20mm (H) x 100mm (L)




Common pipistrelle



East elevation

September 2019



South (inner) elevation

September 2019

Traditional bitumen F1 underfelt will ONLY be used. Access points into the apex box region via modified apex ridge tile as per NE Detail 4B.

