






FRONT ELEVATION 1:50




WESTERN ELEVATION





Access to cavity underneath ridge tiles will be maintained by providing gaps beneath where no mortar will be included.




REAR ELEVATION 1:50

Building B1




SITE LOCATION PLAN 1:1250

A cavity bat box is to be installed on a tree to the north of the barn and on the gable end of the barn where bats were observed emerging from.





One lead bat access tile is to be installed in the southern elevation of the re-roofed building to provide access to tile cavity, only bitumen Type 1RF felt will be installed.

FIGURE E3 Mitigation

ISAAC WALTON FARM

12/05/2021

GRID REF – SJ 97636 39417