
Window 1: 2nd Floor Left




Frame / struts all timber to be primed and painted white

All detailed bevelling etc manufactured as per originals

Middle panel hinged on side outward opening to less than 45 degrees (restricted using opening using original fittings)

18 x single glazed glass panels affixed using putty (to be painted with oil based paint)

Window 2: First Floor Center




Frame / struts all timber to be primed and painted white

All detailed bevelling etc manufactured as per originals

20 x single glazed glass panels affixed using putty (to be painted with oil based paint)

Window 3: First Floor Right




Frame / struts all timber to be primed and painted white

All detailed bevelling etc manufactured as per originals

Middle bottom panel hinged on side outward opening to less than 45 degrees (restricted using opening using original fittings)

30 x single glazed glass panels affixed using putty (to be painted with oil based paint)

Window 4: 1st Floor Side



Frame / struts all timber to be primed and painted white

All detailed bevelling etc manufactured as per originals

Middle panel hinged on side outward opening to less than 45 degrees (restricted using opening using original fittings)

18 x single glazed glass panels affixed using putty (to be painted with oil based paint)

Scale 1:20 - Print at A1 for this Scale