0 2 4 6 8 10m
1:200

T2-Common Lime
T3-Common Lime
T4-Common Lime
T1-Sycamore
T5-Common Lime
T14-Apple
T13-Ash
T12-Ash
H1-Leyland Cypress
T11-Ash
T6-Variegated Norway Maple
T7-Douglas Fir
T8-Norway Maple 'Crimson King'
T10-Cider Gum
T9-Wild Cherry

CONSERVATORY
PROPOSED GARAGE
REMOVE EXISTING GARAGE
Remove Flower Bed
Remove Grass
Remove Vegetation
TURNING AREA
Bulls Head (PH)
HIGH STREET
30
28
24
22
18
1
4

Notes:

1. Contractors are advised to check all dimensions against the tree schedule. Tree canopies are symbolic only and are representative of the average spread; this may not represent the true outline. Note that the tree stem may not sit centrally to canopy. Tree stems are symbolic only and are representative of the tree category; this does not represent the stem diameter - see schedule for details.
2. The original of this drawing was produced in colour - a monochrome copy should not be relied upon.

Rev:	Date:	Status/Amendments:	By:

Key:

- Category A Tree / Group
- Category B Tree / Group
- Category C Tree / Group
- Category U Tree / Group
- Branch Spread
- Tree to be Removed
- Root Protection Area (RPA)
- First Significant Branch Direction
- Root Protective Barrier
- Special Measures
- Tree Shadow

GROWING SINCE 1982
TREE HERITAGE
Tree Heritage Ltd, 100 North Street,
Leek, Staffordshire, ST13 8DQ
Telephone: 01538 384019
treeheritage.co.uk info@treeheritage.co.uk

Client:
Mr & Mrs Ekin

Project:
Blacksmiths Farm House

Drawing Title:
Arboricultural Impact Assessment

Scale:	Paper Size:
1:200	A2
Drawing Number:	Date Created:
THL-0661-2	19/03/2019