IMPACTS PLAN: Structures impacted by works	
Figure reference:	**FIGURE D**
Structure:	Cresswell Ford Farm
Address:	Dilhorne Lane Dilhorne Staffordshire Moorlands ST10 2PH
National GR:	SJ961429
Date:	SEPTEMBER 2019

Aerial view of structure impacted by works (yellow) (source: google earth).



September 2019.

Structrue impacted by works.



East elevation. September 2019.



North-east elevation. September 2019.