Hewitt&CarrArchitects

Condition Discharge Information

00931 – Land Adjacent to Rakeway Grange, Rakeway Road, Cheadle, Staffordshire.
Erection of 6no. Residential Dwellings.

Approval Reference – SMD/2019/0722
October 2020

7. Condition: Contamination

(ii) Following completion of the site remediation and prior to bringing the development into first use, a verification report that demonstrates the effectiveness of the remediation, and containing the information proposed in the CONTAMINATED LAND REMEDIAL STRATEGY (Dated: 15 04 20 No: 19-2123-3) must be submitted and approved in writing by the Local Planning Authority.

Please refer to attached documents :
Topsoil Report - 20-9378-SS - Tarmac Topscape - Eaton Hall Topsoil - Report - Jan 20
Topsoil Delivery Note - Invoice INV-02707
Cover Letter - DCON 7 RAKEWAY ROAD 16.10.20
Verification Report Letter - SLADEN Rakeway Rd Verification Letter Report 15-10-20