

Rock Cottage Farm - Mr & Mrs Knowles
Proposed Alpaca Shelter, Pony Stable and Fodder Store
Tree Report

After visiting the site, the tree preservation officer advised the cutting of some dead/diseased lower branches at T03 (see yellow arrows) and also suggested it would be beneficial to include a few photos in order to give an overall view of the site in relation to the trees. Please therefore see photographs below. Some general sympathetic tidying up and gentle pruning of other lower branches will be undertaken to benefit the site, as advised by the tree officer.

The position has been chosen to maintain a tight connection with the curtilage of the property in order not to be sited in an open position. Any other positioning would entail turning the proposed building facing the on-coming wind direction, thereby negating the effectiveness of the shelter.

