

Tel: 03330 155 166 Email: info@colshawconstruction.com

Appendix B – Photographs

P1 – Trial Pit 1

P2 – Trial Pit 2

P3 – Trial Pit 3

P4 – Indicating slope of paddock



Trail Pit 1 850mm below surface; Before and After Test – water level did not drop



Trial Pit 2 – 500mm below surface - Before and During Test 50% Full level



Trial Pit 3 – 200mm below surface at 75% full level and After test at 25% full level



Photograph 4 indicating slope of land 1 in 20

Yours Faithfully,

Colshaw Construction Ltd

