N

SURVEYED BUILDING EXTENTS WHERE POSSIBLE DUE TO POOR VISIBILITY

EXISTING BUILDING

UNABLE TO SURVEY FFL DUE TO POOR VISIBILITY

SURVEYED BUILDING EXTENTS WHERE POSSIBLE DUE TO POOR VISIBILITY

EXISTING BUILDING

RL158.71

EL157.61

RL156.26

EL155.58

UNABLE TO SURVEY FFL DUE TO POOR VISIBILITY

SURVEYED OVERHEAD CABLES WHERE POSSIBLE OUTSIDE SURVEY AREA

OVERHEAD ELECTRIC CABLES

SURVEYED FENCE LEVELS WHERE POSSIBLE DUE TO DENSE VEGETATION

SURVEYED BOUNDARY EXTENTS WHERE POSSIBLE DUE TO DENSE VEGETATION

SURVEYED WHERE POSSIBLE DUE TO DENSE VEGETATION

SURVEYED BANKING EXTENTS WHERE POSSIBLE DUE TO DENSE VEGETATION

SURVEYED WHERE POSSIBLE DUE TO DENSE VEGETATION

SURVEYED WHERE POSSIBLE DUE TO DENSE VEGETATION

BRAMBLES

GRASS

TARMAC

END OF FENCE

TREE CANOPY

Brookhouse Way

Kenilworth Walk

BROOKHOUSE WAY

UNABLE TO SURVEY FFL DUE TO POOR VISIBILITY

RL161.00 EXISTING BUILDING EL158.92

SURVEYED BUILDING EXTENTS WHERE POSSIBLE DUE TO POOR VISIBILITY

EXISTING BUILDING RL159.96

EL157.61

SURVEYED BUILDING EXTENTS WHERE POSSIBLE DUE TO POOR VISIBILITY

UNABLE TO SURVEY FFL DUE TO POOR VISIBILITY

EL156.25

RL159.89 EXISTING BUILDING

SURVEYED BUILDING EXTENTS WHERE POSSIBLE DUE TO POOR VISIBILITY

UNABLE TO SURVEY FFL DUE TO POOR VISIBILITY

EL156.00

RL159.03 EXISTING BUILDING

SURVEYED BUILDING EXTENTS WHERE POSSIBLE DUE TO POOR VISIBILITY

UNABLE TO SURVEY FFL DUE TO POOR VISIBILITY

EL156.83

RL159.06 EXISTING BUILDING

PROPOSED ROUNDABOUT PEGGED ON SITE

SMALL PEG FLUSHED IN GROUND

0.5m 1.0m 10.0m

scale bar @ 1:200

Cheadle Business Park Ltd

Proposed Commercial Development
Brookhouse Way
Sarraine Industrial Park
Cheadle
Staffs
Existing Conditions
Site Plan

Date	Sheet	Scale
June 2021	A0	1:200
Dwg No.	Rev.	Drawn
2019-2458-01	-	RG

SAMMONS Architectural LIMITED

10 Cawdry Buildings, Fountain Street, Leek. ST13 6JP
Telephone: 01538 386002
E-mail: info@sammonsltd.co.uk
Web: www.sammonsltd.co.uk

This drawing is copyright.
All dimensions must be checked prior to commencement.