



Regarding the removal of asbestos containing materials from the following room(s)/area(s):

Garden

At the following property address:

86 Froghall Road, Stoke-on-Trent, England, United Kingdom.

On: 11/08/2024 (date)

The removal work consisted of:

The removal of 88m2 of asbestos cement profile sheeting

Completed by:

(engineer) Brad Mather

On behalf of: Safe Environment (UK) Ltd
(contractor name and address)

Terminal House, Keighley, BD21 1QQ

I have checked that material was wholly removed and the area was cleaned thoroughly. I inspected the following areas to make sure that there were no visible traces of dust or debris, in addition to the external waste/transit route:

Garden

All Ground Floor Rooms/Areas

All First floor Rooms/Areas

(Areas inspected)

I am satisfied that the area can be returned to normal use.

Signed at:
2024-11-08 16:33:51

Signed: _____

Engineer Name: Brad Mather

Date: 11/08/2024