

Photo No.9

Date: 14/11/2025

Description:

Central chamber in the western extent of the site.



Photo No.10

Date: 14/11/2025

Description:

Drainage dye present in public surface water sewer manhole 5201 (proved connectivity to upstream central chamber).

